



МАШИНА (DYNAMO SLIVEN):

- 1.DC=30V; 3000rpm
- 2.M=0.1Nm
- 3.TACH=3V/1000rpm;
- 4.Rt=456 Ohm(25%С),
Rt=100 Ohm(75%С);
- 5.Rmaschine=3 Ohm

МАШИНА (DYNAMO SLIVEN):

- 1.DC=36V; 1600rpm
- 2.M=0.3Nm
- 3.Km=0.158
- 4.Rmaschine=3.24 Ohm

